

CERTIFICATION by CUSTODIAN of RECORDS Tucson Police Department Crime Laboratory

	~					10	j.
_lolo	by certify that lic maintenand - 004814 Laboratory p	e* for the mainta	Intoxilyze	r 5000 S Tucson	erial Nur Police D	nber Jenartment	
of Put	olic Safety for	a quality	assurance p	rogram.	I the Ariz	ona Departi	nent
dates.	lity assurance The acceptab 0.080AC solut	le accurac	y limits, as	defined	in A.A.C	on the follo . R9-14-404	wing .A.3,
Date:_	1/20/05	Cal 1_	0.075	AC	Cal 2_	0.075	AC
Date:_	2/4/05	Cal 1_	NIA	AC	Cal 2_	NA	AC
Date:_	NA	Cal 1_		AC	Cal 2_		AC
Betwe	en the dates o	f	NA	8	and		
	strument was					1.1	
The in	istrument was istrument was	taken out returned t	of service to to service o	for repain 3	r on	3/4/05 :	*
			let L.			i kure	
		/	1				
		0 0	ennifer L. (
			3/23,	105			
		ADPS (QAS Permit	# QAS	29886		
SU	JBSCRIBED		ORN to be		this	<u>3</u> , da	y of
N KATH	FFICIAL SEAL TY A. KINNEY	,					

*Includes documents specified in A.A.C. R9-14-404.A.6

NOTARY PUBLIC-ARIZONA PIMA COUNTY My Comm. Exp. Sept. 4, 2008

Pursuant to section 28-1327, Arizona Revised Statutes, this document is a certified duplicate of the information contained in computer storage devices of the Tucson Police Department.



MEMORANDUM

DATE:

February 9, 2005

TO:

Whom it may concern

FROM:

Jennifer Coombs

Intoxilyzer 5000 OAS Tucson Police Department

Crime Lab

270 S. Stone Avenue Tucson, AZ 85701-1917

(520) 791-4494

SUBJECT: Intoxilyzer Out of Service

Intoxilyzer 5000, serial number 66-004814, was taken out of service for repair on February 4, 2005.

I cannot testify that it was working properly and accurately between the dates of January 20, 2005 and February 4, 2005.

This instrument was located at ODD.



TUCSON POLICE DEPARTMENT CRIME LABORATORY

INTOXILYZER SERVICE RECORD

Date: February 4, 2005
QAS: Jennifer Coombs 46160
Intoxilyzer Serial Number: 66-004814
Reason For Service: On 2/4/05, Ofc. Nelson left a message stating than the instrument displayed "Out of Range".
Date Out of Service: 3/4/05 Calibration Check completed prior to removal from service
Date: No
SQAP completed prior to removal from service
Date:
Corrective Action:
Instrument brought to lab. During diagnostic test, instrument displayed "Processor Error 5". Plugged pump into fan connector and ran for 1.25 hours. Diagnostic cheeks still produced "Pocessor Error 5"